



RESTORING OF SCRATCHES AND PERSISTENT HALOS - SMOOTH SURFACE (KIT08RG)



1. Scratched or stained surface.



2. Restore kit content




3. Wipe the surface in the direction shown above with the wooden block (D) and sandpaper P180 (A) until the scratch or the stain are removed.




4. To partially restore the surface, use the wooden block (D) with the sandpaper P240 (B).



5. To fulfill the complete restoring on the surface, use the wooden block (D) with the sandpaper P320 (C).



6. Using Scotch Brite (E) wipe the whole surface in the direction shown above to make it matt.



7. By using a small size cloth, spread on the surface some Reviving (F) product, evenly. Wait a few seconds, then swipe off the excess product to avoid sticky surface films.



8. Restored surface.